

## Release Note for VigorSwitch P2282x

Firmware Version:	2.10.6
Loader Version:	3.5.3
Release Type:	Important - Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	VigorSwitch P2282x

VigorSwitch P2282x, 24 Gigabit Ports + 4 SFP (10G) Ports PoE L2 Managed Switch, is a standard switch that meets both IEEE 802.3u/ab Fast Ethernet and Gigabit Ethernet specifications.

### New Features

- None.

### Improvement

- Improved: Improve the CGI security.
- Improved: Updated OpenSSL from v3.6.0 to v3.6.3, incorporating the latest security patches and fixes.
- Improved: Add support for including the device hostname in DHCP Option 12 when sending DHCP requests.
- Improved: Enhance the WUI > Stacking > General Setup page to allow configuration of the Slave device's Stacking Port LAG after stacking is enabled. Add a note indicating that a reboot is required for the changes to take effect.
- Corrected: An issue where the Log Center page on Slave switches loaded slowly in a Stacking environment.
- Corrected: An issue where editing a Protected Host entry after sorting the list displayed an incorrect port number.
- Corrected: An issue where a DHCP Server IP interface with the Pool Count set to 1021 generated an error and could not be saved.
- Corrected: An issue where deselecting SFP+ ports from Stacking did not take effect until the user logged out and logged back in.
- Corrected: An issue where Stacking Port settings were configurable only on the Primary switch and not on Slot (Slave) devices.
- Corrected: An issue where SFP+ ports excluded from Stacking could not be added to a Link Aggregation Group (LAG) on Slot devices.
- Corrected: An issue where the switch rebooted when clearing the Protected Host Table while the

MAC table contained a large number of entries.

- Corrected: An issue where the TR-069 URL on a CPE was not cleared when the device was deleted from ACS with the "Clear TR-069 URL" option enabled.
- Corrected: An issue where LLDP-MED settings were lost after a reboot in a Stacking environment, requiring manual reconfiguration to restore Voice VLAN functionality.
- Corrected: An issue where stale MAC/ARP entries remained on the L3 switch after an HA VIP failover, causing traffic to be forwarded to the previously active node.

## Known Issue

- None.

## Note

- STP (Spanning Tree Protocol) is enabled by default starting from firmware version 2.9.8, which may result in a slightly longer link-up time for ports.