

Release Note for VigorSwitch P2100

Firmware Version:	2.9.11
Loader Version:	3.5.2
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	VigorSwitch P2100

New Features

- None.

Improvement

- Improved: Improve the OpenSSL security.
- Improved: Improved the TR-069 configuration page.
- Improved: Improved the password strength checking method.
- Corrected: An issue with unabling to login to the VigorSwitch WUI due to the web cache.
- Corrected: An issue where the user could not log in to the VigorSwitch WUI after the Eylan logo was added to the login page.

Known Issue

- Users could not downgrade the firmware below 2.8.x, if the loader version is 3.5.2.

Note

- STP (Spanning Tree Protocol) is enabled by default starting from firmware version 2.9.8, which may result in a slightly longer link-up time for ports.