

Release Note for VigorSwitch Q1100x

Firmware Version:	1.58.2
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	VigorSwitch Q1100x

VigorSwitch Q1100x features eight 2.5G Ethernet ports and two SFP ports (10G/2.5G/1G), making it a standard switch that complies with IEEE 802.3u/ab Fast Ethernet and Gigabit Ethernet specifications.

New Features

- Support LED self-test on boot.

Improvement

- Improved: Improve the LLDP web user interface.
- Improved: Increase the LLDP Time to Live up to 120 seconds.
- Improved: Shorten the time spent for the firmware updates via HTTPS.
- Improved: The LLDP ports are enabled in default in Advanced>>LLDP Settings and Status.
- Improved: Display the default username (admin) during the password change for the first time log-in.
- Improved: Add support for sending LLDP System Description and System Capabilities information.
- Corrected: An issue with failure to change the login password after using the translation feature of the browser.
- Corrected: An issue with failure to connect to VigorSwitch via IPv6 HTTPS.
- Corrected: An issue which the DHCPv6 client was unable to get the IPv6 address.
- Corrected: An issue with the failure to display the SFP port link status in the Dashboard while zooming in or out of the webpage.

Known Issue

- When using the SFP module (DrayTek SFP, FPCOPT-RJ-D) for network connections, the transmission speed must be set to 1000 Mbps.

Note

- After upgrading the firmware to version 1.58.2, the device requires 20 to 70 seconds to restart for the first time.